MAY 1886
NEW BRUNSWICK
N.J.

SEE SHEET NO. 7.

SEE SHEET NO. 12.

SEE SHEET NO. 14.

SEE SHEET

RICHMOND

SCHUREMAN

NEW BURNET

NEILSON

JOHN

MORRIS

OLIVER

4" W. PIPE.

104

105

106

103

116

115

Gro.

Dw'g

Dw'g s

Barber.

Sal.

Candy Fruit.

Shoes

Bakery

Vac.

STORAGE.

SHED.

Flour & Feed.

Off.

Hay & Straw W. Ho.

Salt Fertilizers &c.

ELIAS RUNYON & SONS.

14' TO EAVES. 40' TO PEAK OF RF.

Coal Pocket.

STONE CUTT'G.

Grain W. Ho.

Fancy.

Tobac.

Shed.

BOWLING ALLEY.

ICE HO.

Carpt.

B.Sm.

CARR. HO.

GREEN HO.

BR. WALL

BARN.

OVEN.

Bakery

Cigar Mf'r.

Market.

GRAY HO.

Shoe Mf'y.

SHOE MAK'G.

Storage

Candy &c.

Ware Ho.

W. HO.

KILN TILE ROOF.

KILN.

Drying above 1st Eng.

GRINDING & TURNING RM.

FIRE ENG. HO.

Log Pond.

Boat Build'g

YARD.

LUMBER YARD.

ROLFE & SON, SAWING & PLANING MILL & LUMBER

Saw'g & Machinery 1st Saw'g. Lumber 2d

Grist Mill 2d

1 RUN OF STONE.

ENG.

CH. 50'

1. WATCHMAN
NO HEATING APP.
POWER: STEAM.
LIGHTS: KEROS. WHEN USED.
FUEL: SHAVINGS.
ONE 1½ TO 100' 8" RUBBER & 200' 6" LEATHER HOSE.
60' 1½" HOSE IN ENG. RM.

Lumber Shed.

LUMBER SHED.

HOSE HO. & HYD.

DRY HO.

Planing and Sawing.

SHAVGS. PILE.

Lumber Sheds.

Machy 1.2.

Off.

PATTERN SHOP.

NATIONAL IRON WORKS.
W. KELLY.
NIGHT WATCHMAN. STEAM JET 1st & 2d OF MACH. SHOP. OUTSIDE VALVE.
100' 2" HOSE AT IN YARD.
100' 1" " " MACH. SHOP.
25' 1" " " " "
1½" IN PATTERN HO. WITH SPRINKLER ATTACHMENT 2d & 3d CAN BE OPERATED ON 1st FL.
HEAT: STEAM. STOVES IN FOUNDRY.
FUEL: COAL. LIGHTS: GAS. OIL IN FOUNDRY.

CUPOLA

Foundry.

Pattern Storage.

CONC. OVEN

CONC. FLOOR

SAND

CARRIAGE HO.

BRICK WALL 8'

H.V. BUTTLER,
PLAN'G MILL, SASH, D. & B. FAC.
NIGHT WATCHMAN. 600' 1" & 2" HOSE.
1 DOZ. FILLED BUCKETS.
HEAT: EXHAUST STEAM.
FUEL: SHAVGS & COAL.
LIGHTS: GAS.

Grain 2d Open 1st

Coal Shed.

WOOD SAWING. HORSE POWER

WILKINSON

Feed.

Vac. 1st

Gro.

Dry

CARPET WEAVING.

Wooden Pump Fac.

Shed.

Off.

PLANING 1st
STORAGE 1st
SASH, DOOR & BLIND FAC 2d
STORAGE, MOULDINGS 3d

SASH, DOOR & BLIND FAC 2d

PLANING 1st
SASH, DOOR & BLIND FAC 2d
STORAGE, B. & L. BENCH WORK 2d

W I N D O W S

KILNS.

Ware Ho.

Carpt.

STORAGE.

Hardw.

LUMBER.

W. S. VAN DOREN,
SASH, D. B. & MOULD'G FAC.
NO WATCHMAN. 50' 2½" HOSE & HYD. OPPOSITE SIDE OF ST.
HEAT: STEAM & STOVES.
FUEL: SHAVGS. LIGHTS: GAS.

PRINT SHOP 2d

PRINT SHOP

Off.: Storage 2d

LUMBER SHED.

PLANING SASH, DOOR & MOULDING

SAW 1st

SAW 2d

Gro.

Log Pond.

CRONK & VOORHEES BOX FAC.

DRIVE.

Scale of Feet.
50 40 30 20 10 0 50 100 150

NO. 17.

F.H.S. 5-27-86.

MP/3813/NBD/213/1886AH pt 13 of 17